DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-010284 Address: 333 Burma Road **Date Inspected:** 08-Nov-2009

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Mr. An qing xiang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance(QA) Inspector, Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

Machining area

1. This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 040611 perform SMAW repair welding on, inside 89 mtr. Top diaphragm in west tower, Lift 3. The weld joint identified as WSTL3-4 C/K-50. ZPMC CWI Identified as Mr. An qing xiang. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW- 1G (1F)-repair.

2. This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 070140 perform SMAW repair welding on, Skin D fit lug, in west tower, Lift 3. The weld joint identified as WSTL3-4 H/K-85. ZPMC CWI Identified as Mr. An qing xiang. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW- 3G (3F)-repair.

Magnetic Particle Testing:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report for this date. The member is identified as south tower, Lift 3, 89 mtr Diaphragm to Skin D and west tower, Lift 3-99 mtr. Diaphragm to Skin A,B,C,D,E and fit lugs. The weld designations reviewed are as follows:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

WSTL3- 4 G / K – Jt. nos. 49,136,53,65,157,63,76,77,168,169 – 99 mtr.

WSTL3-4 G /K -Jt.nos. 5,6,106,107,108,22,35,130,124 – 99 mtr.

WSTL3- 4 G /K- Jt. nos. 132, 44 – AE and DE corner back fill plates

WSTL3- 4 G /K- Jt. no. 31, 29 – 99 mtr. diaphragm

SSTL3- 1 C/K- Jt. no. 71,82,88 –Skin D – 89 mtr diaphragm

Ultrasonic Testing:

This QA inspector, Baskar Govindarajan, performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted at Tower components by ZPMC Quality Control personnel. This QA Inspector generated a TL-6027 UT report for this date. The member is identified as Back fill plate at outside yard, west tower, Lift 3. The weld designation reviewed is as follows:

WSTL3- 4 G/K - Jt. no -132, 44 - Back fill plate

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge, Sinevod - 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Baskar, Govindarajan	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer